



Section 2'-2'

Mapping of Weathering and Deterioration Forms

LEGEND

Material Loss

Alveolar Decay: Moderate

Alveolar Decay: Severe

Broken stone

Cracks

Erosion

Missing stone

Severe backweathering

Bleach

Exfoliation

Scaling/Delamination

Mechanical Damage

Discolouration and deposits

Black crust

Black crust and biological growth

Cement repairs covering alveolar deterioration/erosion

Superficial deposits: moderate

Superficial deposits: severe

Thick cement plaster

Lime Based Renders

Staining

Other

Cement/Unsound/Empty Joints

Unsound Pointing and Superficial Deposits

Timber Apertures

Apertures

Metal Fixtures

Electrical fixtures

Wood fixtures

Plastic fixtures

Signage

Metal Accretions

Marble

Paint

NOTES

Project	Restoration Tas - Samra, Hamrun	Title	Section 2-2, Deterioration Mapping
Date	27/04/2020	Drawn	BD, NS
Client	Scale 1:50@A2	dwg no	07 56 18

dott. Claude Busuttil perit

ARCHITECTURE & RESTORATION CONSULTANTS

ARCstudio Ltd Suite 7, Level 3, Fafner House, National Road, Blada il-Bajda, Malta
info@arcstudio.com.mt tel +356 2122 8257 fax +356 2122 8257
www.arcstudio.com.mt mob +356 7942 6141

ARC
studio