



1 Dome Facade A














2 Dome Facade B



3 Dome Facade C

5m
2.5
2
1
0
scale 1:50

Legend: Deterioration Mapping

	Alveolisation		Brown deposit		Crack		Missing / Mechanical damage
	Back weathering		Black soiling		Disintegration including Powdering		Erosion including Differential Erosion
	Biological growth		Cement pointing/rendering		Services, cables on surface		

Note: Course lines are for indicative purposes only

Żurrieq Parish Church
client


External Restoration of the Cupola
project

Parish Church of St. Catherine, Misrah ir-Repubblika, Żurrieq
address


ZP-P002
DETERIORATION MAP
drawing

21st SEP 2020
date


1:50
scale



1 Dome Facade D














2 Dome Facade E



3 Dome Facade F

5m
2.5
2
1
0
scale 1:50

Legend: Deterioration Mapping

	Alveolisation		Brown deposit		Crack		Missing / Mechanical damage
	Back weathering		Black soiling		Disintegration including Powdering		Erosion including Differential Erosion
	Biological growth		Cement pointing/rendering		Services, cables on surface		

Note: Course lines are for indicative purposes only

Żurrieq Parish Church
client



External Restoration of the Cupola
project

Parish Church of St. Catherine, Misrah ir-Reppublika, Żurrieq
address


ZP-P002
DETERIORATION MAP
drawing

21st SEP 2020
date


1:50
scale



3 Lantern Facade B



4 Lantern Facade E



Legend: Deterioration Mapping			
	Alveolisation		Brown deposit
	Back weathering		Black soiling
	Biological growth		Cement pointing/ rendering
	Crack		Disintegration including Powdering
	Missing / Mechanical damage		Erosion including Differential Erosion
	Services, cables on surface		

Note: Course lines are for indicative purposes only

Zurrieq Parish Church

client

External Restoration of the Cupola

project

Parish Church of St. Catherine, Misrah ir-Repubblika, Żurrieq

address

ZP-P002

DETERIORATION MAP

drawing

21st SEP 2020

date

1:50

scale