

Side Elevation Z-Z

Mapping of Weathering and Deterioration Forms

LEGEND

Material Loss

- Alveolar Decay: Moderate
- Alveolar Decay: Severe
- Broken stone
- Cracks
- Erosion
- Missing stone
- Severe backweathering
- Efflorescence
- Bleach
- Plant
- Exfoliation
- Collapsed stone
- Scaling/Delamination
- Micro Scalpelling
- Mechanical Damage
- Blistering

Discolouration and deposits

- Black crust
- Black crust and biological growth
- Cement repairs covering alveolar deterioration/erosion
- Superficial deposits: moderate
- Superficial deposits: severe
- Thick cement plaster
- Lime Based Renders
- Staining

Other

- Cement/Unsound/ Empty Joints
- Unsound Pointing and Superficial Deposits
- Timber Apertures
- Apertures
- Metal Fixtures
- Electrical fixtures
- Wood fixtures
- Plastic fixtures
- Signage
- Metal Accretions
- Marble
- Paint

NOTES

Project	Restoration Tas - Samra, Hamrun	Title	Side Elevation, Deterioration Mapping
Date	27/04/2020	Drawn	BD, NS
dwg no	01 56 18		
Client		Scale	1:50@A1

dott. Claude Busuttil perit

ARCHITECTURE & RESTORATION CONSULTANTS

ARCstudio Ltd Suite 7, Level 3, Fafner House, National Road, Blada il-Bajda
info@arcstudio.com.mt tel +356 2122 8257 fax +356 2122 8257
www.arcstudio.com.mt mob +356 7942 6141

ARC studio